

400Vac - 3 phase  
voltage supply

Pe

L1

L2

L3

fuses\*




-DC



L1/L2/N



L3



+

BR

U

V

W



M

