



Spare tubes for air flow indicators type CH25301

Spare tubes for air flow indicator

Application

- For air flow-indicator **CH00216**

Material

- Sulphuric acid in glass tube.